

SUNDARAM BRAKE LININGS LIMITED

Padi, Chennai - 600 050, India.



Telephone: 73580 33474
E-mail : sbl@tvssbl.com
Website : www.tvssbrakelinings.com
PAN : AADCS4888E

27th Nov, 2023

National Stock Exchange of India Limited Exchange Plaza, 5 th Floor Plot No. C/1, "G" Block Bandra Kurla Complex Bandra (East), Mumbai-400 051 Scrip Code: SUNDRMBRAK	BSE Limited Floor 25, P J Towers, Dalal Street, Mumbai – 400 001 Scrip Code: 590072
---	---

Dear Sir/Madam,

**Sub: Intimation of Fire Accident at our Plant -5 – Mahindra World City(SEZ)
Chengalpet – Regulation 30 of SEBI(Listing Obligation and Disclosure Requirements)
Regulations, 2015**

We hereby inform that there was a Fire incidence at our Plant -5 – Mahindra World City(SEZ) during the early morning hours of November,27,2023. While exact cause remains under investigation, we are in the process of assessing the damage caused by the incident. There has been no injury or loss of life. The company has insurance in place for the Plant -5.

This is for your information and records.

Thanking you,

Yours faithfully
for SUNDARAM BRAKE LININGS LIMITED

Y. Sathyan
DGM Finance & Company Secretary

MANUFACTURERS OF TVS BRAKE LININGS & CLUTCH FACINGS

Registered Office : Padi, Chennai - 600 050. India.

CIN : L34300TN1974PLC006703